


Sept. 27/6

## Chapter 2. - Strain

### 2.1 Deformation



Most engineering materials ~ slight deformation



### 2.2 Strain

#### 1) Normal Strain

~ the elongation or contraction by unit of length



Change in length:  $\Delta s = s' - s$

$s'$  = the new dimension

$s$  = the original —

Average normal strain

$$\varepsilon_{\text{avg}} = \frac{s' - s}{s} = \frac{\Delta s}{s}$$

Strain at point A

$$\varepsilon = \lim_{\substack{s \rightarrow 0 \\ (B \rightarrow A)}} \frac{s' - s}{s}$$

If  $\varepsilon$  is known,

$$s' = (1 + \varepsilon)s$$

#### Notes

- If  $\varepsilon > 0$ , the member is subjected to tension
- If  $\varepsilon < 0$ , the member is subjected to compression
- Segment could be a straight line, curve

## 2) Units

$$\epsilon = \frac{S' - S}{S} \quad (\text{no units})$$

(mm/mm) or (in/in) or (mm/m) or (in/in) etc.

Strength  
(Force)


Stiffness  
(deformation)

## 3) Shear Strain

line AB + AC


$$\theta = \pi/2$$

The change in angle is defined between two line segments as:



$$\gamma = \theta - \theta'$$


(gamma) = (theta) - (theta prime)



$\theta = \text{original angle } (\pi/2 \text{ rad}) = 90^\circ$

$$\gamma = 90^\circ - \theta$$

## 4) Cartesian Strain Components




Three deformations

$$\begin{aligned} \epsilon_x, \epsilon_y, \epsilon_z \\ \gamma_{xy}, \gamma_{yz}, \gamma_{zx} \end{aligned}$$

$$\Delta x' = \Delta x (1 + \epsilon_x)$$

$$\Delta y' = \Delta y (1 + \epsilon_y)$$



linear strains change the volume of the

$$\theta_{xy} = \pi/2 (1 + \gamma_{xy}) \quad [\Rightarrow \pi/2 - \gamma_{xy}] \text{ element.}$$

$$\theta_{xz} = \pi/2 (1 + \gamma_{xz}) \quad [\Rightarrow \pi/2 - \gamma_{xz}]$$

$$\theta_{yz} = \pi/2 (1 + \gamma_{yz}) \quad [\Rightarrow \pi/2 - \gamma_{yz}]$$

- Shear strains change the shape of the element
- These two types of deformation occur simultaneously

(3)

### 5) Small strain analysis

only small deformations are allowed

$$\varepsilon \ll 1 \quad (\text{much smaller than } 1)$$

$$\text{Assume } \varepsilon^2 \approx 0$$

$$\text{High order components} \approx 0$$



angular deformation

$$\gamma \approx \text{very small}$$

$$\sin \gamma \approx \gamma$$

$$\cos \gamma \approx 1$$


$$\tan \gamma = \frac{\sin \gamma}{\cos \gamma} \approx \gamma$$

### Assignment Questions

$$\rightarrow 2-3$$

$$\rightarrow 2-29$$

### Example question (2-5)



$$\tan \Theta = \frac{3 \text{ mm}}{150 \text{ mm}}$$


$$\therefore \Theta = 3/150 = 0.02 \text{ rad}$$

Solution

$$\gamma = 90^\circ - (90^\circ + \Theta) = -\Theta$$

$$\gamma_{xy} = -\Theta = -0.02 \text{ rad}$$

$$= -0.02 \times \frac{180^\circ}{\pi} = \text{deg}$$



$$l_{CD} = \sqrt{(150)^2 + (200)^2}$$

$$l_{CD} =$$

$$l'_{CD} = \sqrt{(150)^2 + (200+3)^2}$$

$$l'_{CD} =$$

$$\sum_{CD} = \frac{l'_{CD} - l_{CD}}{l_{CD}}$$



$$\Delta_{CBD'} = \frac{l'_{CD} - l_{CD}}{l_{CD}}$$

Sept. 29 / 18

## Chapter 3: Mechanical Properties of Materials

## 3.1 Tension and compression Test

- used for metals, polymer, ceramics

Force  $P$  (measured by load cell)

$$\text{Deformation} = \delta = l - l_0$$

(measured by ~~extens~~ gauges)  
strain

$$\epsilon = \delta/l_0$$

$$\sigma = F/A = \frac{P}{\pi d^2/4}$$

area of cylinder face

## 3.2 Stress-Strain Diagram

Average stress


Uniformly distributed

$$\sigma = F/A = \left( \cancel{\frac{P}{\pi d^2}} \right) \rightarrow \left( \frac{P}{\pi d_0^2} \right)$$

write as

Average strain

$$\epsilon \text{ constant between gauge marks } \epsilon = \delta/l_0$$

 $\sigma_{pl}$  = proportional limit

elastic region - if the ~~force~~ (load)  $\sigma_f$  is removed the specimen will return to normal to its original shape.

 $\sigma_e$  = elastic limit


From  $\sigma_{pl}$  to  $\sigma_e$  is no longer linear.  
 $\sigma$  (region)

Plastic behavior: permanent deformation occurs.

 $\sigma_y$  = yielding $\sigma_u$  = ultimate limit $\sigma_f$  = fracture stress\* Assume  $\sigma_{pl}$ ,  $\sigma_e$ ,  $\sigma_y$  coincide:  
unless specified otherwise

- engineering design occurs in elastic region (mostly)

- necking is when material becomes smaller (in terms of  $d_0$ ) and can't support original stress.



(2)

C content  $< 0.35\%$ . (low carbon) ~ low carbon  
 (carbon) Steel - alloy with C, Fe, ... steel C + Fe  
 (alloy)

ductile { C content  $< 0.35\%$  ~ low C steel  
 C content  $0.35 \sim 0.6\%$  ~ medium C. steel  
 brittle { C content  $> 0.6\% \sim (1.2/1.3)$  ~ high C. steel  
 $(\sigma - \epsilon)$

### 3.3 Stress-strain behavior of ductile and brittle materials

Materials can be classified as either ductile or brittle

ductile  
 brittle

#### 1) Ductile materials

~ be subjected to large strains before failure

~ can absorb impacts. overloading

- percent elongation

$$PE = \frac{L_f - L_o}{L_o} \times 100\%$$

$L_f$  = length at Failure

$L_o$  = original length

- Percent reduction in area

$$PR = \frac{A_o - A_f}{A_o} \times 100\%$$

$A_o$  = original area

$A_f$  = Area in fracture

- PE  $> 5\%$  ~ ductile material

PE  $< 5\%$  ~ brittle material

#### 2) Brittle materials:


PE  $< 5\%$

~ little or/no yielding before Failure

Sept. 30 / 16

(Question 1-64 From Chapter 1)

Method 1:




$$+ \uparrow \sum F_y = 0$$

$$-F_{AB} + F_{AC} (\cos \alpha) = 0$$

$$\therefore F_{AC} (4/5) = \frac{4}{5} F_{AB}$$

$$\frac{4}{5} F_{AB} = (\frac{4}{5})(4/5) = 4$$

Point C



$$+ \rightarrow \sum F_x = 0 \quad (\cos \alpha)$$


$$F_{BC} - F_{CD} \cos \alpha = 0$$

$$F_{BC} = F_{CD} \cos \alpha$$

$$F_{CD} = 8 \text{ kip}$$

oops..

Point B



$$\sum F_x = 0$$

$$\therefore F_{BC} = -6 \text{ kip (c)}$$

$$+ \rightarrow \sum F_x = 0$$

$$6 \text{ kip} + F_{ACx} - F_{CDx} = 0$$

$$6 \text{ kip} + (3/5) F_{AC} - (3/5) F_{CD} = 0$$

$$\Rightarrow F_{CD} = 15 \text{ (Tension)}$$

$$+ \uparrow \sum F_y = 0$$

$$G_{CE} = \frac{-16 \times 10^3 \text{ lb}}{1.25}$$

$$15 \cdot \cos \alpha - F_{CD} \cos \alpha - F_{CE} = 0$$

$$F_{CE} = -16 \text{ kip (comp.)}$$

... no answer.

Example 2-14 (From textbook.)

$$l_{AB} = 1000 \text{ mm}$$

$$l_{AB'} = \sqrt{\overline{AC}^2 + \overline{CB'}^2 + 2\overline{AC} \cdot \overline{CB'} \cos(90^\circ + 0.5^\circ)}$$

$$= \cancel{1000} 1004.18 \text{ mm}$$

$$\xi_{AB} = \frac{l_{AB'} - l_{AB}}{l_{AB}} = 0.00418 \text{ mm/mm}$$